

8&C -Photo 109. Interior stair tower with moderate to severe corrosion.



8&C -Photo 110. Underside of interior stair tower with moderate to severe corrosion.



8&C -Photo 111. Typical corrosion on underside of southwest stair tower landings.



8&C -Photo 112. Typical worn paint on stair tower railings.

