

City of Columbia Historic Preservation Commission Application for Most Notable Property

Community Development Department, Planning Division City of Columbia, 701 E. Broadway, Columbia, MO 65201 Planning@CoMo.Gov

Address Being Nominated 901 THILLY AVENUE
Date Property Built (if known) 1914
First Owner/Builder/Architect (if known) ARCH TEZT: JAMES UAMIESON
Current Owner's Name <u>GREG & MELISSA HAGEN</u> (properties may be nominated by non-owners but owners must give permission for photography/videography of property- see page 2 for release)
Address 702 THILLY AVENUE
Phone Number 5732688023 E-mail MGMHAGEN@HOTMAIL COM
Submitter's Name MELISSA HAGEN
Submitter's Phone number 573 268 8023 E-mail MOM HAGE NO HOTMAIL. WM

NOTE: The following information provides a starting point for historic research on the property. However, a lack of information should not be a deterrent for an application. All properties chosen for Most Notable will have a history of the property compiled by a historic preservation professional. This history will be provided to property owners for their own records.

Has anyone of local, regional, or national historic note ever occupied the property? If so, whom?

OD, KELLOGG - MATHMATICS PROFESSOR AT UNIVERSITY OF MISSONRI,

THMOUS FOR HIS TEXTBOOK "FOUNDATIONS OF POTENTIAL THEORY", ALSO

GENERALIZED THE BIRKHOFF. KELLOGG THY ARIANT. DIRECTION THEOREM

Does the property have any notable or unusual architectural qualities? If so, please identify.

ORIGINAL POURD GLASS WINDOWS, MUDING & DOORS & POCKET DOOR

EXTERIOR IS DOUBLE WALL OF RED BRICK & AIR SPACE BETWEEN WHICH

HOLDS REGULATE TEMPERATURE (INTERIOR) ALL YEAR.

PROFESSIONALLY DESIGNED BY SAMESLAMIESON- ARCHITECT, NOTED FOR MATNY BUILDINGS ON MU LAMPUS, MULLIDING ELLIS LIBRARY, FAMOUT FIELD, JESSE HALL 1953
Have any recent renovations been performed that have helped restore the property? If so, describe them RENOVATION-briefly. WE ARE ATTEMPTING TO FIND A CONTRACTOR TO REPAIR

- . DARMER & PORCH RAILINGS THAT ARE STARTING TO ROT.
- · BRICK PATIO WAS WORKED ON TO REPLACE CRUMBLING BRICK
- FIRST PLOOR WOOD PLOURS WERE REFINISHED

Is the property recognized by any other historic preservation organizations? If so, please identify.

	(signature)
Melissa Higen 5	124/2022
3	
2	_
1. PRONT OF THUSE-DELOY	VAL WOOD WIRK, DOOR, WINNOOW & CORMER
Rooms/elements of interest in the buildi	ing's interior:
* *	nications to photograph and video record up to three ilding (optional- will require owner's presence)
(signature)	(signature)
Chelissa Hagen	
	online in an interactive historic map (required for nomination)
	nications to photograph/video record around exterior property and
ICE CELIVERY DOOR	
	THIS SAZE.
SHUTE, BUT WAS RECENT Please attach current and/or early pic	MENTWALL I THINK THIS WAS A COAL TEMPS of the property. IN THIS DAZE.
· UTTLE DOOR IN THE BASE	MENTWALL I THINK THIS WAS A COAL
2 ND FLOW OPPICE HAS A	N MECHED DOOR, VERY UNIQUE.
	IS IN GREAT SHAPE FOR ITS AGE.
To the state of th	a - American A and and





























