



Notes on Alignments

"Minimal Ability to Modify" indicates that the alignment is highly constrained by terrain and there is little potential for flexibility in the alignment. However, as additional survey work is completed, the alignment may need to be fine tuned to better address the constraints.

"To Be Adjusted to Stay Within Sewer Easement and Previously Cleared Areas" indicates that it is our intent that the final alignment will be adjusted to stay within existing easements and cleared areas because there are no significant constraints dictating that the alignment shown is the only option

"Limited Ability to Modify" means that we drew the alignment to have the minimal impact on the property given constraints we are aware of while trying to produce a trail that meets minimum requirements for accessibility and safety. If there are constraints that we did not anticipate, there may be some potential to realign to avoid them while maintaining trail quality.

Legend

- Trail Alignments**
- Preferred Alignment - Minimal Ability to Modify
 - Preferred Alignment - To Be Adjusted to Stay Within Sewer Easement and Previously Cleared Areas
 - Preferred Alignment - Limited Ability to Modify
 - Proposed Rollins Connector Trail
 - - - Sanitary Sewer - From City Shapefile
 - Sewer Manholes - From City Shapefile
 - Approximate Property Boundaries
 - Pending 100 Year Floodplain
 - Pending Floodway
 - Existing Ground - 5ft Contours

**Hinkson Trail Project
Proposed Alignment
Columbia, MO**

Job Number: 16043.01

Sheet:
1 of 1

REUSE OF THIS DRAWING IN
ANY MANNER IS STRICTLY
PROHIBITED WITHOUT THE
WRITTEN APPROVAL OF
ALLSTATE CONSULTANTS LLC

Print Date: 1/27/2017



**ALLSTATE
CONSULTANTS**
3312 LEMONE INDUSTRIAL BLVD.
COLUMBIA, MO. 65201
(672) 875-4799
allstateconsultants.net



200 0 200 400 ft