

AFFIDAVIT
(June 30, 2023)


Re: An error in reporting the bearing of a line called out in the 9th line of the 3rd paragraph and located in section 14, township 48 north, range 12 west, Boone County, Missouri.

STATE OF MISSOURI)
COUNTY OF BOONE) ss.

I David W. Borden, of lawful age, being duly sworn upon my oath state as follows:

1. I am a Missouri Registered Land Surveyor and that I prepared the description for an annexation tract recorded in Book 5760, pages 89, records of Boone County, Missouri.
2. That in the bearing, along the west line of a survey and tract described in Book 3181, Page 13, is reported as S 1°11'00"W in the description. The correct bearing should be reported as **S 1°11'00" E**.
3. The rest of the survey and bearings are otherwise correct.

Further affiant saith naught.



David W. Borden, Professional Land Surveyor
PLS-2002000244

Subscribed and sworn to before me, a notary public, this 30th day
Of June, 2023.



Danielle Griffith, Notary Public
My Commission Expires: October 28, 2024
Commission Number 12409201

