






**Water Play Structure Replacement**



**Water Play Structure Area Aggregate Flooring Replacement**




**Aquatics Office Area and Party Room Flooring Replacement**

# Building Foundation Repairs: Representative Settlement Issues



ARC Entry Area




Exterior Meeting Room Wall


## Building Foundation Repairs: Representative Settlement Issues



Office Area Overhang



Front Service Entry



Mechanical Room



**Domestic Hot Water Heater Replacement**