

MKT Bridge Replacement Project Photos  
Condition of Bridges 5, 7 and 8



Bridge No. 5



Bridge No. 5 Support Structure Deterioration



Bridge No. 5 Prior to Temporary Repair Work



Bridge No. 5 After Temporary Repair Work



Bridge No. 7



Bridge No. 7 Support Structure Deterioration



Bridge No. 7 Temporary Repair Prior to Rip-Rap



Bridge No. 7 After Temporary Repair Work in 2015



Bridge No. 8



Bridge No. 8 Support Structure Problems