


Domestic Hot Water Heater Replacement


Elevator Maintenance and Updates

Building Foundation Repairs: Representative Settlement Issues



ARC Entry Area


Exterior Meeting Room Wall



Office Area Overhang



Aquatics Office Area and Party Room Flooring Replacement




Front Service Entry



Water Play Structure Replacement



Water Play Structure Area Aggregate Flooring Replacement



Mechanical Room

# Activity Recreation Center (ARC) Proposed Improvements

December 19, 2022

