





Domestic Hot Water Heater Replacement

Elevator Maintenance and Updates

Building Foundation Repairs: Representative Settlement Issues



ARC Entry Area




Exterior Meeting Room Wall



Office Area Overhang





Aquatics Office Area and Party Room Flooring Replacement



Water Play Structure Replacement




Water Play Structure Area Aggregate Flooring Replacement



Front Service Entry



Mechanical Room



Activity Recreation Center (ARC) Proposed Improvements

December 19, 2022

